

**HUB CITY
IRON WORKS**

PCM Backplate Plain Linear Bearing Upgrade


THE Pipe Yard Equipment Company!

Plain Bearings = Less Downtime. Plain & Simple.


Due to the dirty environments found in Pipe Cleaning Machines, a common cause of downtime is the failure of Backplate Linear Bearings. Bearing failures such as these can be troublesome to replace because of their location. Hub City is happy to announce a solution to this problem:

The PCM Backplate Plain Linear Bearing Upgrade!


- Ball bearing design is more prone to failure, especially if not greased.
- Requires more maintenance.



- Frelon type plain bearing requires no maintenance.
- Inherently less prone to failure due to less moving parts.
- Sealed with Rod Wiper to keep out contaminants.
- Chrome plates rod provides excellent rust protection.
- Reverse compatible with most Hub City machines
- Plain bearings can be replaced much more cost effectively.



Standard ball bearing type linear bearing shown.



Upgraded Plain Bearing and Rod style Rail shown. (Cutaway shown for clarity)